




44




45



46



47



49




48

RAMMED MOIST FRESH EARTH - NABÍJENICE / FORMWORK WITH HORIZONTAL TIMBERS PASSING THROUGH THE WALL:: 44 -46 Rammed earth walls of the barn; Spinek (Hodonín) * **47** Detail of the filling of the hole; Kozojídky (Hodonín) * **48** Rammed earth barns; Vnorovy (Hodonín) * **49** Granulometric diagram of rammed earth constructions studied in the project Analysis of historic earthen materials in Czech Republic (J. Kříž 1996 - 1998)



50



51



55



56



52



53



54

RAMMED MOIST FRESH EARTH - NABÍJENICE: 50 Rendered and whitewashed barn; Spinek (Hodonín) * 51 -53 Barn with remaining pieces of rendering; Spinek (Hodonín) * 53 - 54 - Details of stone plinth; Spinek (Hodonín), Liděřovice (Hodonín) * 55 - 56 Details of the wall coping; Liděřovice (Hodonín)



57



58



59



60



61

RAMMED MOIST FRESH EARTH - NABÍJENICE: **57** Reinforcement of the corner; Lidéřovice (Hodonín) * **58** Reinforcement by wattle; Jankovice (Uherské Hradiště) * **59 - 61** - Farmhouse; Spinek (Hodonín): detail of the rammed earth visible under the rendering / detail of the cornice from fired bricks